



11 December 2020

Part Discontinuation Notice

Effective immediately, Magnetics powder core finish code A5 is no longer being offered. Improvement in the guaranteed performance of A2 coating has rendered A5 coating unwarranted. Cores with finish code of A2 are now rated for 2000 V_{AC} minimum voltage breakdown (wire-to-wire), which is the same as the performance formerly offered with A5.

Last time buy orders only will be accepted only if the product(s) are currently in stock. New orders will not be accepted.

We appreciate your business and regret any inconvenience caused.

Please contact your Magnetics Sales Engineer or Customer Service Representative, or email magnetics@spang.com, with questions or concerns.