

MAGNETICS A Division of Spang & Company 110 Delta Drive, PO Box 11422 Pittsburgh, PA 15238-0422 U.S.A.

3 March 2017 Posted 30 November 2018

Beginning Q4 2017, Magnetics will be discontinuing the nylon coating process (V) for ferrite cores due to environmental compliance regulations beyond our control. Our recommended replacement for nylon coating is epoxy (Z) coating.

If you require nylon coating, please contact your existing vendor no later than **July 24, 2017** to place a last time buy purchase order for your required quantities. Afterwards, only purchase orders for cores which consume unsold inventory will be accepted.

Thank you for your business. We look forward to working with you to ensure a smooth transition.

•

٠