

17 December 2018

Part Discontinuation Notice

Effective immediately, the part number(s) listed below are no longer being offered by Magnetics. Last time buy orders only will be accepted only if the product(s) are currently in stock. New orders will not be accepted.

Recommended replacements may not have the same dimensions or materials. Please contact engineering with questions regarding product similarities and differences.

Part Number(s) Discontinued	Recommended Replacement(s)
PCB151081	PCB15108A

We appreciate your business and regret any inconvenience caused.

Please contact your Magnetics Sales Engineer or Customer Service Representative, or email <u>magnetics@spang.com</u>, with questions or concerns.