

10 July 2023

## Part Change Notice

Effective immediately, the following products will be pressed using chamfers to reduce production scrap. Photos showing product with and without chamfered edges are shown below for comparison.

| Product(s) Affected |                    | Recommended Replacement(s) |
|---------------------|--------------------|----------------------------|
|                     |                    | 1                          |
| 5528 Size E Cores   | 5530 Size E Cores  | N/A                        |
| including, but not  | including, but not |                            |
| limited to:         | limited to:        |                            |
| 00A5528E026         | 00A5530E040        |                            |
| 00F5528E026         | 00A5530E060        |                            |
| 00G5528E060         | 00G5530E060        |                            |
| 00K5528E026         | 00K5530E026        |                            |
| 00K5528E040         | 00K5530E040        |                            |
| 00K5528E060         | 00K5530E060        |                            |
| 00K5528E090         | 00K5530E090        |                            |
| 00X5528E026         | 00X5530E026        |                            |
| 00X5528E040         | 00X5530E040        |                            |
| 00X5528E060         | 00X5530E060        |                            |
| 00Y5528E026         | 00Y5530E026        |                            |
| 00Y5528E040         | 00Y5530E040        |                            |
| 00Y5528E060         | 00Y5530E060        |                            |

Please contact your Magnetics Sales Engineer or Customer Service Representative, or email <a href="magnetics@spang.com">magnetics@spang.com</a>, with questions or concerns.



