



21 February 2019

### Part Discontinuation Notice

Effective immediately, the part number(s) listed below are no longer being offered by Magnetics. Last time buy orders only will be accepted only if the product(s) are currently in stock. New orders will not be accepted.

| <b>Part Number(s) Discontinued</b> | <b>Recommended Replacement(s)</b> |
|------------------------------------|-----------------------------------|
| PCB2318T1                          | None                              |
| PCB2318B1                          | None                              |

We appreciate your business and regret any inconvenience caused.

Please contact your Magnetics Sales Engineer or Customer Service Representative, or email [magnetics@spang.com](mailto:magnetics@spang.com), with questions or concerns.