



MAGNETICS

A Division of Spang & Company
110 Delta Drive, PO Box 11422
Pittsburgh, PA 15238-0422 U.S.A.

March 3, 2017

Beginning Q4 2017, Magnetics will be discontinuing the nylon coating process (V) for ferrite cores due to environmental compliance regulations beyond our control. Our recommended replacement for nylon coating is epoxy (Z) coating.

If you require nylon coating, please contact Magnetics Customer Service no later than **August 1, 2017** to place a last time buy purchase order for your required quantities. After August 1, we will only accept purchase orders for cores that consume unsold inventory.

Thank you for your business. We look forward to working with you to ensure a smooth transition.

Sincerely,

Grace Anewalt
Marketing Specialist
Magnetics, a division of Spang & Company